Maryland Historical Trust

Maryland Inventory of Historic Properties number: WA-I-757

Maryland Inventory of Historic Properties number:	1-75+
Name: US 1) order Potoma	Co Ruer & WMBZ
The bridge referenced herein was inventoried by the Maryland St Historic Bridge Inventory, and SHA provided the Trust with elig The Trust accepted the Historic Bridge Inventory on April 3, 200 determination of eligibility.	ibility determinations in February 2001.
MARYLAND HISTORICAL	
	Eligibility Not RecommendedX
Criteria:ABCD Considerations:A _	BCDEFGNone
Comments:	
Reviewer, OPS:_Anne E. Bruder	Date:3 April 2001
Reviewer, NR Program: Peter E. Kurtze	Date: 3 April 2001

Maryland Inventory of Historic Properties Historic Bridge Inventory Maryland State Highway Administration Maryland Historical Trust MHT Number WA-I-737

Name and SHA No. US 11 over Potomac River and Western Maryland RR/21001 (2100110)

Location:	
Street/Road Name and Number: US Route 11	
City/Town: Williamsport Vicinity x	
County: Washington	
Ownership: x State County Municipal Other	
This bridge projects over: _Road_x_Railway_x_Water_Land	
Is the bridge located within a designated district: _yes_x_no	
_NR listed district_NR determined eligible district _locally designated_other Name of District	
Bridge Type:	
_Timber BridgeBeam BridgeTruss-CoveredTrestleTimber-and-Concrete	
_Stone Arch	
_Metal Truss	
_Movable BridgeSwingBascule Single Leaf_Bascule Multiple LeafVertical LiftRetractile_Pontoon	
 <u>x</u> Metal Girder _Rolled Girder _Rolled Girder Concrete Encased _x Plate Girder _Plate Girder Concrete Encased 	
_Metal Suspension	

_Meta	l Arch
_Meta	l Cantilever
_Conc	rete
	_Concrete Arch _Concrete Slab_Concrete Beam
	_Rigid Frame
	Other Type Name

Description:

Describe Setting:Bridge 21001 (2100110) carries US Route 11 over the Potomac River and the Western Maryland Railroad. US 11 runs in an east-west direction at this location; the Potomac flows north-south and the railroad runs generally north-south. The bridge is located just outside the small town of Williamsport. The West Virginia bank of the Potomac is wooded; the Maryland side has the railroad, associated industrial structures and open fields.

Describe Superstructure and Substructure:Bridge 21001 (2100110) is a 17 span welded plate girder bridge. Thirteen of the spans are 100' long; 2 are 89'; one is 118'; one is 89'. The total bridge length is 1,680'. The bridge deck is concrete with bituminous overlay on the wearing surface of the roadway. There are concrete jersey barrier walls along both sides of the deck the entire length of the bridge. For approximately the first 50' of the east and west end of the bridge there is a chain link protective fence attached to and projecting up from the jersey walls. The rest of the deck has W-beam guardrails attached to the top of the jersey walls. There is a date plaque at the entrance to the bridge on the Maryland side, north elevation. The superstructure is in good condition, with flaking paint and some rusted areas.

The substructure is made up of two concrete abutments and wing walls and 16 concrete solid shaft piers, with concrete collars and bases. The abutments and piers are in good condition, with some cracks and spalling. There is no evidence of severe undermining or scour at the bases of the piers.

Discuss Major Alterations:Bridge 21001 (2100110) was rehabilitated in 1980. At this time major repairs were made to the floor system and beams, with several of them being replaced. The deck was also replaced at this time, as well as repairs to the abutments. In 1991 emergency repairs were made to 4 of the 20 piers. These 4 piers were not founded in rock as the others were. One of the 4 piers had settled several inches, making the bridge extremely hazardous for travel. The allowable live load weight was decreased dramatically and all 4 piers were reinforced by underpinning.

History:

When Built:1909,

Why Built: local transportation needs

Who Built:

Why Altered: to improve structural stability

Was this bridge built as part of an organized bridge building campaign:no

Surveyor Analysis:

This bridge may have NR significance for association with:

_A Events _B Person

_C Engineering/Architectural

Was this bridge constructed in response to significant events in Maryland or local history: It is likely that the original 1909 bridge was built to replace an older less stable structure, and may be directly related to the Western Maryland Railroad.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area: The original structure probably did have a significant impact on the development and growth of the area surrounding Williamsport, both on the Maryland and West Virginia sides of the Potomac River.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from historic and visual character of the possible district:no

Is the bridge a significant example of its type:Bridge 21001 (2100100) is a significant example of a welded plate girder of above average length. However, it was rehabilitated in 1980.

Does the bridge retain integrity of the important elements described in the Context Addendum: The 1980 plate girder bridge does retain all of its original structural elements, therefore retaining its integrity.

Is the bridge a significant example of the work of the manufacturer, designer, and/or engineer and why: It is of above average length, and could be considered an unique example of a plate girder bridge erected by the State Roads Commission in the late 20th century.

Should this bridge be given further study before significance analysis is made and why: No, this structure does not warrant further study.

Bibliography:

Greiner, Inc.

1995 Historic Bridge Inventory Form.

Spero, P.A.C. & Company, and Louis Berger & Associates

1994 Historic Bridges in Maryland: Historic Bridge Context.

State Highway Administration

v.d. Bridge Inspection Files.

United States Geological Survey


1979 7.5' Williamsport Quadrangle.

Surveyor:

Name: Stephanie L. Bandy Date: September 1995

Organization: State Highway Admin. Telephone: (410) 321-2213

Address: 2323 West Joppa Road Brooklandville, MD 21022





WAY BP7 1 00/10) 2 171/ 2/35/55

1 01 3



WA 1 37 (32#2/00/10) 2001 POTOPHE FIER & W. HD. IT LEED - FRUE 2 44 : 2 TOPTE HODE INTERFORM



y+ 5-1/34 (38# - 10-1/10) =1-4 HAKLEL ZYKSEK 2/22/95 S. H. X

. *∪* £ 3